



1. The locking mechanism is opened by depressing the latches with hand application tool (PN 1971903-1) as shown in Figure 13.
2. Disconnect the connectors connection while the special tool insertion into the locking mechanism to depress the latches, and pull the connectors apart.



Figure 13
Disconnect the connectors

3. For installation application, it can use opening tooling to tighten operation in Figure 14



Figure 14
Tightening the connectors with Opening tool